



15 MINUTE SKI TUNING MAINTENANCE SYSTEM

CHECKLIST:

Step One (Base Edge Tuning)

- Unstrap and dry cold/wet skis
- Put elastics on ski brakes
- Clean the skis base with Brass Brush
- Verify base bevel & if concave or convex with True Bar
- Base edge polishing (when needed)

Step Two (Side Edge Tuning)

- Side edge filing with File Guide (when needed)
- Side edge maintenance with Diamond Guide (120-1000 grit discs)
- Remove micro burr with gummi stone (when needed)

Step Three (Waxing)

- Clean base structure with Brass Brush
- Wax the skis
- Scrape while warm when using Nanox Wax
- Brush & polish with nylon brush when using Nanox Wax
- Use three ski straps

The logo for Nanox, featuring the word "nanox" in a bold, lowercase, sans-serif font. The text is black and is centered within a solid yellow rectangular background.