

Checklist:

4 Step Ski Tuning System (for brand new skis)

Step One (Base Edge Tuning)

- Put *Elastics* on brakes
- Clean base with *Brass Brush*
- Verify base bevel & if concave or convex with *True Bar*
- *Base Bevel* Filing (150-250mm Files)
- *Base Bevel* Polishing (Diamond Stones)

Step Two (Sidewall Preparation)

- Remove Sidewall with *Sidewall Remover*
- Top sheet clearance (tip and tail)
- Sidewall blending and polishing

Step Three (Side Edge Tuning)

- Set edges with 120-200 grit disc on *Diamond Guide*
- Side edge filing with *File Guide*
- Side edge polishing with *Diamond Guide* using 400-1000 grit discs
- Remove micro burr with *Gummi Stone*

Step Four (Waxing)

- Clean base structure with *Brass Brush*
- Wax the skis
- Scrape while warm when using *Nanox Wax*
- Brush & polish with *Nylon Brush* when using *Nanox Wax*
- Use 3 *Ski Straps*



Checklist:

15 Minute Ski Tuning Maintenance System

Step One (Base Edge Tuning)

- Unstrap and dry cold/wet skis
- Put *Elastics* on ski brakes
- Clean the skis base with *Brass Brush*
- Verify base bevel & if concave or convex with *True Bar*
- *Base edge* polishing (when needed)

Step Two (Side Edge Tuning)

- Side edge filing with *File Guide* (when needed)
- Side edge maintenance with *Diamond Guide* (120-1000 grit discs)
- Remove micro burr with *Gummi Stone* (when needed)

Step Three (Waxing)

- Clean base structure with *Brass Brush*
- Wax the skis
- Scrape while warm when using *Nanox Wax*
- Brush & polish with *Nylon Brush* when using *Nanox Wax*
- Use 3 *Ski Straps*

